

**The Bosch LH 2.4 Jetronic System is used on the 89–93 models  
(and later non-turbo/non-ODBII models)**

- 1-1-1 No faults.
- 1-1-2 Control unit fault.
- 1-1-3 Fuel injectors – Injector cable break or blocked injector; 1994– Heated Oxygen sensor – max. enrichment sensed
- 1-1-5 Injector #1.
- 1-2-1 No signal to or from air mass meter. Engine runs in limp-home mode.
- 1-2-2 Air temp sensor signal.
- 1-2-3 No signal from coolant temperature sensor, or short to ground. Engine behaves as thought hot.
- 1-2-5 Injector #2.
- 1-3-1 Ignition system RPM signal missing.
- 1-3-2 Battery voltage to low or high.
- 1-3-3 Throttle switch idle position incorrectly adjusted or shorted to ground.
- 1-3-5 Injector #3.
- 1-4-2 Control unit fault. Engine running in limp-home mode with safety-retarded ignition (10°)
- 1-4-3 Knock sensor signal missing or defective. Engine running in limp-home mode with safety-retarded ignition (10°)
- 1-4-4 Fuel system load signal is absent or defective (air mass meter). Unit selects full-load timing and runs in limp-home mode.
- 1-4-5 Injector #4.
- 1-5-3 Rear heated Oxygen sensor signal.
- 1-5-4 EGR system-leakage or excessive flow.
- 1-5-5 Injector #5.
- 2-1-2 Oxygen sensor (Lambdasond) signal missing (front sensor on 1994 and later models).
- 2-1-3 Throttle switch in full load position, shorted to ground.
- 2-1-4 Ignition RPM signal erratic (sensor faulty).
- 2-2-1 Adaptive Lambda control, lean, part load; also heated Oxygen Sensor (Lambdasond), rich mixture / part load.
- 2-2-2 Main relay.
- 2-2-3 No signal to or from idle control valve.
- 2-2-4 Coolant temperature sensor faulty. Engine behaves as thought hot and runs in limp-home mode.
- 2-2-5 A/C pressure sensor signal.
- 2-3-1 Adaptive Lambda control, lean or rich / part load.
- 2-3-1 Adaptive Lambda control, lean or rich, part load; 1994– Heated Oxygen sensor(lean mixture/part throttle).
- 2-3-2 Adaptive Lambda control, lean or rich / idle; 1994– Adaptive heated Oxygen sensor control
- 2-3-3 Idle control valve, closed or leaking.
- 2-3-4 Throttle switch (idling) signal missing. Engine running with safety-retarded ignition (10°)
- 2-4-1 Exhaust gas recirculation (EGR) malfunction. Not applicable to B234F
- 2-4-5 Idle air control valve-closing signal.
- 3-1-1 No signal from speedometer.
- 3-1-2 No knock enrichment signal from ignition system.
- 3-1-4 Camshaft position signal missing or defective.
- 3-1-5 EVAP emission control system.
- 3-2-1 Cold start valve-signal missing.
- 3-2-2 Air mass meter platinum wire burn-off function defective.
- 3-2-4 Camshaft position signal erratic.
- 3-2-5 ECU memory failure.
- 3-3-5 TCM request for MIL.

4-1-1 Throttle switch signal faulty or missing.

4-1-3 EGR temperature sensor signal incorrect or missing. Not applicable to B234F

4-1-4 Turbo boost regulation.

4-1-6 Turbo boost reduction from TCM.

4-2-5 Temp warning level #1.

4-3-1 EGR temp sensor faulty or missing.

4-3-2 High temp warning inside ECU.

4-3-3 No rear knock sensor signal.

4-3-5 Front heated oxygen sensor – slow response.

4-3-6 Rear heated oxygen sensor compensation.

4-4-3 Catalytic converter efficiency.

4-4-4 Acceleration sensor signal.

4-5-1 Misfire – #1 cylinder.

4-5-2 Misfire – #2 cylinder.

4-5-3 Misfire – #3 cylinder.

4-5-4 Misfire – #4 cylinder.

4-5-5 Misfire – #5 cylinder.

5-1-1 Adaptive oxygen sensor control–lean mixture at idle.

5-1-2 Oxygen integrator at max lean running limit.

5-1-3 High temp warning inside ECU.

5-1-4 Engine cooling fan–low speed signal faulty.

5-2-1 Oxygen sensor preheating–front.

5-2-2 Oxygen sensor preheating– rear.

5-3-1 Power stage–group A.

5-3-2 Power stage–group B.

5-3-3 Power stage– group C.

5-3-4 Power stage– group C.

5-3-5 TC control valve signal.

5-4-1 EVAP valve signal.

5-4-2 Misfire – more than one cylinder.

5-4-3 Misfire – at least one cylinder.

5-4-4 Misfire – more than one cylinder/catalytic converter damage.

5-4-5 Misfire – at least one cylinder/catalytic converter damage.

5-5-1 Misfire – #1 cylinder/catalytic converter damage.

5-5-2 Misfire – #2 cylinder/catalytic converter damage.

5-5-3 Misfire – #3 cylinder/catalytic converter damage.

5-5-4 Misfire – #4 cylinder/catalytic converter damage.

5-5-5 Misfire – #5 cylinder/catalytic converter damage.

## The FENIX 5.2 System is used on the 10 valve non turbo 850

- 1-1-1 No faults
- 1-1-2 ECU faulty
- 1-1-3 Fuel injectors; From 1994 and later, Heated oxygen sensor – max. enrichment sensed short term fuel mixture too weak
- 1-1-5 Injector no. 1 cylinder faulty signal
- 1-2-1 Manifold Absolute Pressure (MAP) signal absent or faulty
- 1-2-2 Air Temperature sensor signal absent or faulty
- 1-2-3 Coolant temperature sensor signal absent or faulty
- 1-2-5 Injector no. 2 cylinder faulty signal
- 1-3-1 Ignition System RPM signal
- 1-3-2 Battery voltage too low/high
- 1-3-3 Throttle switch signal (idle)
- 1-3-5 Injector no. 3 faulty signal
- 1-4-2 ECU faulty
- 1-4-3 Front knock sensor signal missing or sensor defective
- 1-4-4 Fuel system load signal (missing or defective)
- 1-4-5 Injector no. 4 cylinder faulty signal
- 1-5-2 Air pump valve signal absent or faulty (only on some emission controlled vehicles)
- 1-5-3 Rear heated oxygen sensor signal
- 1-5-4 EGR system – leakage or excessive flow
- 1-5-5 Injector no. 5 cylinder faulty signal
- 2-1-2 Heated Oxygen sensor signal (front sensor on 1994 and later models) absent or faulty
- 2-1-3 Throttle switch signal (wide-open)
- 2-1-4 Ignition rpm sensor signal erratic, absent or faulty
- 2-2-1 Lambda Operation; Also heated Oxygen sensor (rich mixture/part throttle) / long term fuel mixture too weak in part load
- 2-2-2 Main relay signal absent or faulty
- 2-2-3 Idle air control valve signal absent or faulty
- 2-2-4 Coolant temperature sensor signal
- 2-2-5 A/C pressure sensor signal absent or faulty
- 2-3-1 Lambda adjustment; Also heated Oxygen sensor (lean mixture / part throttle) / long term fuel mixture too rich in part load
- 2-3-2 Lambda adjustment; 1994– adaptive heated oxygen sensor control / long term fuel mixture too weak at idle
- 2-3-3 Idle valve – closed or intake air leak / long term idle air trim outside control range
- 2-3-4 Throttle switch signal missing
- 2-4-1 EGR malfunction
- 2-4-5 Idle air control valve – closing signal
- 3-1-1 Speedometer signal
- 3-1-2 Knock/Fuel enrichment signal missing
- 3-1-4 Camshaft position sensor signal missing or defective
- 3-1-5 EVAP emission control system
- 3-2-1 Cold start valve – signal missing
- 3-2-2 Airflow meter hot wire
- 3-2-4 Camshaft position sensor signal erratic
- 3-2-5 ECU memory failure
- 3-3-5 TCM request for MIL (CHECK ENGINE light)
- 4-1-1 Throttle switch signal faulty or missing

- 4-1-3 EGR temperature sensor signal incorrect or missing
- 4-1-4 Turbo boost regulation
- 4-1-6 Turbo boost reduction from TCM
- 4-2-5 Temperature warning level no. 1
- 4-3-1 EGR temperature sensor faulty or missing
- 4-3-2 High temperature warning inside ECU
- 4-3-3 No rear knock sensor signal
- 4-3-5 Front heated oxygen sensor – slow response
- 4-3-6 Rear heated oxygen sensor compensation
- 4-4-3 Catalytic converter efficiency
- 4-4-4 Acceleration sensor signal
- 4-5-1 Misfire cylinder no. 1
- 4-5-2 Misfire cylinder no. 2
- 4-5-3 Misfire cylinder no. 3
- 4-5-4 Misfire cylinder no. 4
- 4-5-5 Misfire cylinder no. 5
- 5-1-1 Adaptive oxygen sensor control, provides leaner mixture at idle
- 5-1-2 Oxygen intergrator at maximum lean running limit
- 5-1-3 High temperature warning inside ECU
- 5-1-4 Engine cooling fan – low speed signal faulty
- 5-2-1 Oxygen sensor preheating front
- 5-2-2 Oxygen sensor preheating rear
- 5-3-1 Power stage – group A
- 5-3-2 Power stage – group B
- 5-3-3 Power stage – group C
- 5-3-4 Power stage – group D
- 5-3-5 TC control valve signal
- 5-4-1 EVAP valve signal
- 5-4-2 Misfire on more than one cylinder
- 5-4-3 Misfire on at least one cylinder
- 5-4-4 Misfire on more than one cylinder, catalytic converter damage
- 5-4-5 Misfire on at least one cylinder, catalytic converter damage
- 5-5-1 Misfire on cylinder no. 1, catalytic converter damage
- 5-5-2 Misfire on cylinder no. 2, catalytic converter damage
- 5-5-3 Misfire on cylinder no. 3, catalytic converter damage
- 5-5-4 Misfire on cylinder no. 4, catalytic converter damage
- 5-5-5 Misfire on cylinder no. 5, catalytic converter damage

## **The Motronic 4.3 System is used on the 20 valve turbocharged and some non-turbo 20 valve B5254S engines**

- 1-1-2 ECU faulty
- 1-1-5 Injector no. 1 cylinder faulty signal
- 1-2-1 MAF signal absent or faulty
- 1-2-3 Coolant temperature sensor signal absent or faulty
- 1-2-5 Injector no. 2 cylinder faulty signal
- 1-3-1 Ignition System RPM signal absent or faulty
- 1-3-2 Battery voltage too low/high
- 1-3-5 Injector no. 3 faulty signal
- 1-4-3 Front knock sensor signal missing or sensor defective
- 1-4-4 Fuel system load signal (missing or defective)
- 1-4-5 Injector no. 4 cylinder faulty signal
- 1-5-2 Air pump valve signal absent or faulty (on certain engines)
- 1-5-4 EGR system – leakage or excessive flow (on certain engines)
- 1-5-5 Injector no. 5 cylinder faulty signal
- 2-1-2 Heated oxygen Sensor Signal absent or faulty
- 2-1-4 Ignition rpm sensor signal intermittently absent
- 2-2-3 Idle air control valve signal absent or faulty
- 2-2-5 A/C pressure sensor signal absent or faulty
- 2-3-1 Long term fuel mixture too lean or rich in part load stage
- 2-3-2 Long term fuel mixture too lean or rich at idle
- 2-3-3 Long term idle air trim outside control range
- 2-3-5 EGR controller signal absent/faulty (on certain engines)
- 2-4-1 EGR flow fault (on certain engines)
- 2-4-3 Throttle position sensor signal voltage incorrect (out of range)
- 2-4-4 Knock control at limit
- 2-4-5 Idle air control valve closing signal faulty/absent
- 3-1-1 Speedo signal missing
- 3-1-3 EVAP valve signal absent/faulty (on certain engines)
- 3-1-4 Camshaft position sensor signal missing or defective
- 3-1-5 EVAP emission control system fault (on certain engines)
- 3-2-3 Malfunction indicator lamp signal faulty
- 3-2-5 ECU memory failure
- 3-3-5 Request for Malfunction indicator lamp signal from auto transmission ECU
- 3-4-2 Airconditioning relay control signal fault
- 3-4-3 fuel pump relay control signal fault
- 4-1-1 Throttle position sensor signal not within correct voltage
- 4-1-3 EGR temperature sensor signal incorrect or missing (on certain engines)
- 4-1-4 Turbo boost pressure too high
- 4-1-6 Turbo boost reduction from auto transmission ECU(/TCM)
- 4-3-2 High temperature warning inside ECU
- 4-3-3 Rear knock sensor signal absent/faulty
- 4-3-5 Heated oxygen sensor – slow response
- 4-4-2 Air pump relay signal absent/faulty (on certain engines)

- 5-1-1 Long term fuel mix too rich @ idle
- 5-1-2 Short term fuel mix too rich @ idle
- 5-1-3 High temperature warning inside ECU
- 5-1-4 Engine cooling fan at low speed faulty
- 5-1-5 Engine cooling fan at high speed faulty
- 5-2-1 Oxygen sensor heating fault
- 5-2-3 Signal to ECU module box cooling fan shorted to 12 volts
- 5-2-4 Fault in transmission torque control signal
- 5-3-5 Turbo regulator valve fault
- 5-4-1 EVAP valve signal fault (on certain engines)

**The Bosch LH 3.2 Jetronic system is used on the 20 valve non-turbocharged except some B5254S engines using Motronic.**

- 1-1-1 No faults
- 1-1-2 ECU faulty
- 1-1-3 Short term fuel mixture too weak
- 1-2-1 MAF signal absent or faulty
- 1-2-3 Coolant temperature sensor signal absent or faulty
- 1-3-1 Ignition System RPM signal absent or faulty
- 1-3-2 Battery voltage too low/high
- 2-1-2 Heated oxygen Sensor Signal absent or faulty
- 2-2-1 Long term fuel mixture too weak in part load stage
- 2-2-3 Idle air control valve signal absent or faulty
- 2-3-1 Long term fuel mixture too lean or rich in part load stage
- 2-3-2 Long term fuel mixture too lean, idle
- 3-1-1 Speedometer signal missing
- 4-1-1 Throttle position sensor signal absent
- 5-1-1 Long term fuel mix too rich, idle
- 5-1-2 Short term fuel mix too rich